

# **TEST REPORT**

Applicant:	SHANTOU CITY CHENG PLASTIC TOYS FACTOR SOUTH SIDE OF DENGF GUANG YI STREET CHE SHANTOU CITY GUANG CHINA 515800	FENG ROAD ENGHAI DISTRICT	Number: Date:	HKGH02500942 Aug 27, 2019
Submitted sam Item Name Item No.	ple said to be	ZC7097, ZC7096, ZC7095 ZC7089, ZC7088, ZC7087 ZC7080, ZC7079, ZC7078 ZC7072, ZC7071, 7069, 7 7060, 7059, 7058, 7057, 7 7039, 7038, 7037, 7036, 7 7025, 7024, 7023, 7022, 7 7006, 7005, 7004, 7003, ZC04, ZC05, ZC06, ZC0	2, ZC7101, Z 5, ZC7093, Z 7, ZC7086, Z 3, ZC7077, Z 068, 7067, 7 056, 7055, 7 036A, 7035, 7021, 7020, 7002, 7001, 8, ZC09, Z	C7100, ZC7099, ZC7098, C7092, ZC7091, ZC7090, C7083, ZC7082, ZC7081, C7076, ZC7075, ZC7073, 7066, 7065, 7063, 7062, 7061, 7054, 7053, 7052, 7051, 7050,
Labelled Age G Packaging Prov Country of Orig Quantity	vided	: 8+ : Yes. : CHINA. : Each 6 Pieces.		******

Conclusion:

The submitted sample was tested under the following requirements requested by the applicant, subject to the information stated in the remark and attached page(s) for details :

	Requirement	<u>Result</u>
(1)	REACH Regulation (EC) No. 1907/2006, Annex XVII item 5 & amendment No. 552/2009	Pass
	- Benzene content requirement	
*****	***************************************	*****

For and on behalf of : Intertek Testing Services HK Ltd.

Cindy I.K. Chan Director

## 

Intertek Testing Services Hong Kong Limited

Tel +852 2173 8888 Fax +852 2786 1903 intertek.com.hk





# **TEST REPORT**

Number : HKGH02500942

#### (1) Benzene Content

Test Method : By Head Space Gas Chromatographic - Mass Spectrometric (HS GC-MS) analysis.

Tested Component	Result in ppm	Limit in ppm
(1/2/3)	<0.5	5
(4/5)	<0.5	5
(6/7/8)	<0.5	5
(9/10/11)	<0.5	5
(12/13/14)	<0.5	5
(15)	<0.5	5
(16/17)	<0.5	5
(18)	<0.5	5

ppm = parts per million = mg/kg

**Tested Components:** 

- Blue plastic with coatings (gun).
- Orange plastic (gun).
- (1) (2) (3) (4) (5) (6) (7) (8) (9) (10) Dark grey plastic (grip, gun).
- Transparent plastic (gun).
- Green plastic (bullet holder). Yellow foam (bullet).
- Red foam (bullet).
- Orange plastic (bullet).
- Translucent glue (wire holder) (internal).
- Black plastic (switch of slide switch, button of press switch) (internal).
- Brown PCB (PCB of slide switch, press switch) (internal). (11)
- (12) Black plastic (wire covering) (internal).
- Red plastic (wire covering) (internal). Black plastic (leaf switch) (internal). (13)
- (14)
- (15) Plastic parts of white motor (internal).
- (16)White plastic (gear) (internal).
- Yellow plastic (trigger holder) (internal). (17)
- Plastic parts of black motor (internal). (18)

Date sample received : Aug 20, 2019

Test Period : Aug 20, 2019 to Aug 22, 2019 \*\*\*\*\*



Intertek Testing Services Hong Kong Limited

2/F Garment Centre 576 Castle Peak Road Kowloon, Hong Kong

Tel +852 2173 8888 Fax +852 2786 1903 intertek.com.hk



### **TEST REPORT**

Number : HKGH02500942





### End of report

Except where explicitly agreed in writing, all work and services performed by Intertek is subject to our standard Terms and Conditions which can be obtained at our website: http://www.intertek.com/terms/. Intertek's responsibility and liability are limited to the terms and conditions of the agreement.

This report is made solely on the basis of your instructions and / or information and materials supplied by you and provide no warranty on the tested sample(s) be truly representative of the sample source. The report is not intended to be a recommendation for any particular course of action, you are responsible for acting as you see fit on the basis of the report results. Intertek is under no obligation to refer to or report upon any facts or circumstances which are outside the specific instructions received and accepts no responsibility to any parties whatsoever, following the issue of the report, for any matters arising outside the agreed scope of the works. This report does not discharge or release you from your legal obligations and duties to any other person. You are the only one authorized to permit copying or distribution of this report (and then only in its entirety). Any such third parties to whom this report may be circulated rely on the content of the report solely at their own risk.

This report shall not be reproduced, except in full.





Intertek Testing Services Hong Kong Limited

2/F Garment Centre 576 Castle Peak Road Kowloon, Hong Kong Tel +852 2173 8888 Fax +852 2786 1903 intertek.com.hk